

FIELD INSPECTION REPORT

Date of Inspection :	20-12-2020	District:	PURNEA
Division :	DEAMDATA	Length (km):	2.20 K.M
Name of the Road:	TO 5 se DAMHARA DAS TOLA.		
Scheme/Programme:	MAINTENANCE		
Package No.:	M.M.G.S.Y.	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/V
b)	Condition of Surfacing	S/V
c)	Riding Quality	S/V
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/V
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/V
c)	Condition of railings/slab/approach for Bridges	S/SRI/V
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Pranav
20-12-2020
(Signature)

NAME: PRANAV KUMAR
(Signature)