FIELD INSPECTION REPORT

Date of Inspection: 07-12-2020		District: 130,84 champaran	
Division: pakridya		Length (km): 1.264	
Name of the Road: Ko	iri Tola Banch	to jitaura math	
	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance —		
Work is a case of:	New Connectivity/Up gradation/ Maintenance —		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	-15.5.15
a)	Road Junction condition	SHU
b)	Condition of Surfacing	\\$#U
c)	Riding Quality	\$/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	&/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S∕SRI⁄U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

07 12 2020 (Signature)

NAME: Dharmentora Kumar

DESIGNATION: JE