

FIELD INSPECTION REPORT

Date of Inspection : 21/12/20	District : Nalanda
Division : Hilsa	Length (km) : 0.670 km
Name of the Road : Kaji Bipla road to Rani pur Kala	MMGSY
Scheme/Programme : MAINTENANCE	Maintenance
Package No.:	Road Id No.:
Status of the Project : Ongoing/Completed/Under Maintenance	Under Maintenance
Work is a case of : New Connectivity/Up gradation/ Maintenance	Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S
a)	Road Junction condition	U S
b)	Condition of Surfacing	U S
c)	Riding Quality	U S
d)	Road Camber	U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes No Yes
g)	Compaction of flank/slope & raincuts if any	Yes No
2.	Cross Drainage	Record screen
a)	Condition of head walls or Hume pipe culverts including its painting	S RTI S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S RTI S
c)	Condition of railings/slab approach for bridges	S RTI S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes No Yes
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Praful Kumar Arya
S.E

[Signature]
21/12/20