


FIELD INSPECTION REPORT

MMWY 3C

Date of Inspection :		District: <u>Nasik</u>
Division : <u>Maharashtra</u>		Length (km): <u>0.60 km</u>
Name of the Road: <u>Bela Dargah P.A. Chowdhary Road - Kumbharwadi Phartur</u>		
Scheme/Programme:		MAINTENANCE <input checked="" type="checkbox"/>
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	<input checked="" type="checkbox"/> S/U
b)	Condition of Surfacing	<input checked="" type="checkbox"/> S/U
c)	Riding Quality	<input checked="" type="checkbox"/> S/U
d)	Road Camber	<input checked="" type="checkbox"/> S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<input checked="" type="checkbox"/> Yes/No
f)	Contraction Joints provided or not (CC Pavement)	<input checked="" type="checkbox"/> Yes/No
g)	Compaction of flank/slope & raincuts if any	<input checked="" type="checkbox"/> Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	<input checked="" type="checkbox"/> S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<u>M.A</u> S/SRI/U
c)	Condition of railings/slab/approach for Bridges	<u>N.A</u> S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<input checked="" type="checkbox"/> Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


12.12.20
AE
15.12.20
AE

(Signature)

NAME:

DESIGNATION: