

FIELD INSPECTION REPORT

MMWY SC

Date of Inspection :	13.12.20	District: Vanu Lali'
Division :	Mahua	Length (km): 0.950
Name of the Road: Agarwala Khund P.A. Jahu Pokhar to Ramchandrapur <i>Region</i>		
Scheme/Programme:	MAINTENANCE ✓	
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N. ✓A-S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N. ✓A-S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

*✓ 13.12.20
S. S. 15/12/20 AE*

(Signature)

NAME:

DESIGNATION: