

FIELD INSPECTION REPORT

Date Of Inspection	19/12/2020	District	Bhojpur
Division	Pi-20	Length (km):	0.800
Name of the Road:	Dharampura to Dharampura Mahadallitola.		
Scheme/Programme	MAINTENANCE		
Package No.:	Road Id No.: 10401813016		
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
SI No.	Parameters to be checked	Remarks	
1	Payment		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	" SRI "
Unsatisfactory (U)	

Name: Ashok Kumar

(Signature)
19/12/2020

Designation J.E.