


FIELD INSPECTION REPORT

Date of Inspection :		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 0.370 km	
Name of the Road : Kathara (Nishara) Madan Mandal house to Thiwani Mandal house			
Scheme / Programme : I			
Package No : MMGSY (GEN)		Road Id No : 2070322035	
Status of the Project : Ongoing / Completed / Under Maintenance ✓			
Work is a case of : New Connectivity / Up gradation / Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No ✓	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes / No	
g)	Compaction of flank/slope & raincuts if any	✓ Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	NA
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No ✓	
4.	Compliance History		
a)	Status of ATR's & any others	NO	
Overall Rating			
	Satisfactory (S)	1	
	Satisfactory but requires Improvement (SRI)	SRI	
	Unsatisfactory (U)	1	

Note : Logo board not properly maintained km 200m stone not found

NAME : Rutisha Rajah
DESIGNATION : A.E


Signature 18.12.2020