


# FIELD INSPECTION REPORT

| Date of Inspection : 18.12.2020   |   | District : Bhagalpur      |      |
|---|---|---------------------------|------|
| Division : Bhagalpur  |   | Length (Km) : 0.570 km    |      |
| Name of the Road : Mahadevita to Kasmabad house of Sakeldeo house to horiyasi (shakunda road) |   |                           |      |
| Scheme / Programme :  |   |                           |      |
| Package No. : MMGSX (SC)  |   | Road Id No. : 20703213019 |      |
| Status of the Project :   Ongoing / Completed / Under Maintenance ✓                           |   |                           |      |
| Work is a case of :   New Connectivity / Up gradation / Maintenance                           |   |                           |      |
| Sl. No.   | Parameters to be checked  | Remarks                   |      |
| 1.  | <b>Pavement</b>   |                           |      |
| a)  | Road Junction condition   | S/U ✓                     |      |
| b)  | Condition of Surfacing  | S/U ✓                     |      |
| c)  | Riding Quality  | S/U ✓                     |      |
| d)  | Road Camber   | ✓ S/U                     |      |
| e)  | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                                  | Yes / No ✓                |      |
| f)  | Contraction Joints provided or not (CC Pavement)  | Yes / No                  |      |
| g)  | Cmpaction of flank/slope & raincuts if any  | Yes / No ✓                |      |
| 2.  | <b>Cross Drainage</b>   |                           |      |
| a)  | Condition of head walls in Hume pipe culverts including its painting  | S / SRI / U               | ] NA |
| b)  | Condition of Abutment & Wing Walls, Slab in RCC culverts  | S / SRI / U               |      |
| c)  | Condition of railings/slab/approach for Bridges   | S / SRI / U               |      |
| 3.  | <b>Road Furniture</b>   |                           |      |
| a)  | Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained. | Yes / No ✓                |      |
| 4.  | <b>Compliance History</b>   |                           |      |
| a)  | Status of ATR's & any others  | No                        |      |
| <b>Overall Rating</b>   |   |                           |      |
|   | Satisfactory (S)  | 1                         |      |
|   | Satisfactory but requires Improvement (SRI)   | 1                         |      |
|   | Unsatisfactory (U)  | U                         |      |

Note : B.T crust damage in some part Logo board not properly maintain

NAME: Rajkishor Rajak  
DESIGNATION: A.E

  
Signature 18.12.2020  
A.E