FIELD INSPECTION REPORT

Date of Inspection : \Q	12 20 20	District: Gobelson			
Division: Gobalgo		Length (km):			
Name of the Road: M/R Kanhang NH20 to Sisaya bely techic road					
Scheme/Programme:	MAINTENANCE				
Package No.:		Road Id No.:			
Status of the Project:		/Under Maintenance			
Work is a case of:	New Connectivity/U	Jp gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	a Kin

N·A

Note-Out of mountenance. 5 Lears
maintence not povison in DPR.

(Signature)

WAIVIE.

HY KUMARTIWAR

DESIGNATION:

E.E.