

FIELD INSPECTION REPORT

2013-14

Date of Inspection : 20.12.20	District: Buxar
Division : Buxar	Length (km): 2.8 km
Name of the Road: Dadara for Nohar to Chaudhri	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 2.8 km length is maintained
Status of the Project: Ongoing/Completed/Under Maintenance	rest 500m length is
Work is a case of: New Connectivity/Up gradation/ Maintenance	not under maintenance.

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N/A
b)	Condition of Surfacing	S/U N/A
c)	Riding Quality	S/U N/A
d)	Road Camber	S/U N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No N/A
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

2.3 km road length is maintained & rest road length 500m is not under maintenance.

20.12.20

(Signature)

NAME: N.K. Himanshu
सहायक अभियंता
राजपुर विभाग
का. ज. न. न. न. राजपुर

सहायक अभियंता
ग्रा. विभाग
का. ज. न. न. न. राजपुर