

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: Buxar
Division : RWD, Buxar	Length (km): 1.30 KM.
Name of the Road: Dullapur More in Simri Sonbaria Rd to Balihar school More.	
Scheme/Programme:	MAINTENANCE Out of Maintenance
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road-Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA
4.	Compliance History	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	This road is out of five year maintenance.
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

03/12/2020
J.E, Simri

(Signature)

NAME:

DESIGNATION:



CamScanner