

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: Buxar	
Division : RWD, Buxar		Length (km): 1.00 Km.	
Name of the Road: C/Agou broken than in new Bhojpur Rd to Khorha Tand.			
Scheme/Programme:		MAINTENANCE out of maintenance.	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	-S/U	NA
b)	Condition of Surfacing	-S/U	NA
c)	Riding Quality	-S/U	NA
d)	Road-Camber	-S/U	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope : rinecuts if any	Yes/No	
a)	Condition of head walls in Lume pipe culverts including its painting	-S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-S/SRI/U	NA
c)	Condition of railings/slab/s. porch for Bridges	-S/SRI/U	NA
a)	Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	NA
a)	Status of ATR's & any others	NO	

Overall Rating

Satisfactory (S)	This road is out of five year maintenance.
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

03/12/2020

J.E. Simri

(Signature)

NAME:

DESIGNATION:

