

FIELD INSPECTION REPORT

Date of Inspection : 03/12/020	District: Buzas
Division : RWD, Buzas	Length (km): 2.200 KM.
Name of the Road: Simri to Balihas high school.	
Scheme/Programme:	MAINTENANCE out of Maintenance
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

S. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of Subgrade & Base Course	Yes/No NA
	Condition of head walls in Retaining walls including its painting	S/SRI/U NA
e)	Condition of Abutment & Wing wall, Slab in RCC culverts	S/SRI/U NA
c)	Condition of approach for Bridges	S/SRI/U NA
	Whether sign boards/informatory/correctionary Board/ km & 300m stones/Pavement road markings are provided and maintained	Yes/No NA
a)	Status of ATR's & any other	NO

Overall Rating

Satisfactory (S) This road is out of five year maintenance	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Room
03/12/020
J.E. Simri
(Signature)

NAME:

DESIGNATION:



Scanned with
CamScanner