

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: Buxar
Division : RWD, Buxar	Length (km): 6.100 KM.
Name of the Road: Smri Prakhad anjagat Smri se tilal, rai ke hatat.	
Scheme/Programme:	MAINTENANCE out of Maintenance.
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

S. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SFC NA
b)	Condition of Surfacing	SFC NA
c)	Riding Quality	SFC NA
d)	Road Camber	SFC NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & runouts if any	Yes/No NA
a)	Condition of head walls in Home pipe culverts including its painting	S/SB/I/L NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SB/I/L NA
c)	Condition of railing/slab approach for Bridges	S/SB/I/L NA
a)	Whether sign boards/informatory/cautionary Board/km & 200m survey/Pavement road markings are provided and maintained	Yes/No NA
b)	State of PATR's & any others	NO

Overall Rating:

Satisfactory (S) This road is out of live for maintenance.	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Ram
03/12/2020
JE, Smri

(Signature)

NAME:

DESIGNATION: