

# FIELD INSPECTION REPORT

Date of Inspection :	21-12-2020	District:	PURNEA
Division :	PURNEA	Length (km):	6.55
Name of the Road:	Dhan Kharika RCO road to Lagan Kamalpur road		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	MEA 220001903
Status of the Project:	<input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/> New Connectivity/Up gradation/ Maintenance		
Work is a case of:			

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	SU
b)	Condition of Surfacing	SU
c)	Riding Quality	SU
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

*Kamlesh Chaudhary*  
21/12/20  
(Signature)

NAME: Kamlesh Chaudhary  
DESIGNATION: CE-3