

FIELD INSPECTION REPORT

Date of Inspection :	21-12-2020	District:	PURNEA
Division :	PURNEA	Length (km):	8.56.
Name of the Road:	Repair of road from Jagdi Chauk Singhia (Arariya) Simla		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	21105208102
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	SA ✓
d)	Road Camber	SA ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No } N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U } N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U } N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U } N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

(Signature)

NAME:

Rambh Chaudhary

DESIGNATION:

CE-3.