

# FIELD INSPECTION REPORT

Date of Inspection : 21.12.2020		District: W. Champaran
Division : RWD, works, D.V. Bagaha		Length (km): 7.00 (3.70) Km.
Name of the Road: PWD Road to Pathari		
Scheme/Programme:		MAINTENANCE
Package No.: RM/WE/BAG/190021		Road Id No.: 31901031857
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance New Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
f)	Contraction Joints provided or not (CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	yes
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	— N.V.

S.C. Parameter is provided

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

3.3 km constructed by sugar mill  
S.L.R. Bridges required at ca. 420m & 490m  
21/12/2020  
(Signature)

NAME: Ratnesh Paswan  
DESIGNATION: Executive Engineer.