

FIELD INSPECTION REPORT

Date of Inspection :	20/11/2020	District :	Madhya Pradesh
Division :	Madhya Pradesh	Length (km) :	5.100
Name of the Road :	Charhara to Gollan Panga		
Scheme/Programme :	MAINTENANCE		
Package No. :		Road Id No. :	0.1004700032
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U	
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

The work has not been started. The road is in very bad condition.

W/cm
20/11/2020
(Signature)

NAME:

SANSEER KUMAR

DESIGNATION:

EXECUTIVE ENGINEER
CE-3 Jt, Road, Patna