FIELD INSPECTION REPORT

		FIELDINSLES		
Date of	Inspection: 2	1.12.2020	District: Nalande	
Distator			1 11 /km): 2.5 FL	
Name of the Rout: 1/462 Se Tiuri Janewali fork Ki Myamme				
Scheme	Luckramme:	MAINTENANCE	MR -3034	
Package No.:			Road Id No.:	
Status of the Project: Ongoing/Comple			//Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance		Remarks
Sl. No.	Parameters to be checked			
1.	Pavement			S/U SV
a)	Road Junction condition			
b)	Condition of Surfacing			S/U U
c)	Riding Quality			S/U U
d)	Road Camber			S/U U
e)	Whether free from defects such as visible cracks, exposed yes/No/			Yes/No NO
f)	Contraction Joints provided or not (CC Pavement)			Yes/No -
g)	Compaction of flank/slope & raincuts if any			Yes/No No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U U			S/SRI/U U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U			S/SRI/U
c)	Condition of railings/slah/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No			
4.54	Compliance History			
a)	Status of ATR	s & any others		_

Overall Rating

Satisfactory (S)	_
Satisfactory but requires Improvement (SRI)	_
Unsatisfactory (U)	U

NAME: Rank Basin Kemps Singh DESIGNATION: Encentive Expined

Scanned with CamScanner