

FIELD INSPECTION REPORT

Date of Inspection : 20/12/20	District: East Champaran
Division : Chakia	Length (km): 3.10
Name of the Road: NH 28 (Brdwa) To Madhu Chap Chhapra	
Scheme/Programme: MAINTENANCE	
Package No.: ☒	Road Id No.: 31708202136
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	New MR

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	<u>S</u>
Satisfactory but requires Improvement (SRI)	<u>—</u>
Unsatisfactory (U)	<u>—</u>

NAME:

Brdwa Rajak

DESIGNATION:

Executive Engineer

R-W.D.

Regional Laboratory Darbhanga

(Signature) 20/12/20