

5

FIELD INSPECTION REPORT

Date of Inspection : 21/12/20
 District: East Champaran
 Division : Areraoj
 Length (km): 2.07
 Name of the Road: Gay Ghat Bazar to Dih Tola charholi to Mahua Nerresh mamjhi das
 Scheme/Programme: MAINTENANCE
 Road Id No.:
 Package No.:
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity Up gradation Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ SU
b)	Condition of Surfacing	✓ SU
c)	Riding Quality	✓ SU
d)	Road Camber	✓ SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ SRI U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI U
c)	Condition of railings/slab approach for Bridges	S SRI U N/A
3.	Road Furniture	
a)	Whether sign boards, informatory cautionary Board, km & 200m stones, Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of AIR's & any others	N/A

Overall Rating :
 Satisfactory (S) S
 Satisfactory but requires Improvement (SRI)
 Unsatisfactory (U)

[Signature]
 21/12/20
 (Signature)

NAME: Bindu Rajak
 DESIGNATION: Executive Engineer
 R.W.D.
 Regional Laboratory Darbhanga