

FIELD INSPECTION REPORT

Date of Inspection : 21.12.2020		District: W. Champaran	
Division : RWD, Works Div. Bagaha-1		Length (km): 3.20 Km.	
Name of the Road: Ram Nagar to Nadda			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.: 31809008074	
Status of the Project:		Ongoing/Completed/Under Maintenance M/R 305-4	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others — NO	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

N.A

date of completion: — 6-10-2020

According to the Road is out of maintenance

(Signature) 21.12.2020

NAME: Ratnesh Paswan

DESIGNATION: Executive Engineer