

FIELD INSPECTION REPORT

Date of Inspection : 21.12.2020		District: W. Champaran
Division : RWD works Div. B999A-1		Length (km): 13.07 km.
Name of the Road: Dhanra Bazar to Banwari		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 31809008076
Status of the Project: Ongoing/Completed/Under Maintenance		MR-3054
Work is a case of: New Connectivity/Up gradation/ Maintenance		


Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	<div style="font-size: 3em;">}</div> pot develop in AT portion. —
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	— SRI
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	— SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4.	Compliance History	
a)	Status of ATR's & any others	— NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	— SRI
Unsatisfactory (U)	

NAME: Ratnesh Paswan

DESIGNATION: Executive Engineer


 (Signature) 21.12.2020