

FIELD INSPECTION REPORT

Date of Inspection : 21.12.2020		District: W. Champaran
Division : RWD, works Div. Bagaha-I		Length (km): 4.74 km.
Name of the Road: PWD Road to Kori Banjar		
Scheme/Programme: MAINTENANCE		
Package No.: RM/WE/13AG/20/004		Road Id No.: 31809102025
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance <i>New Maintenance</i>

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

N.A.
work has not started
Notice issued.

21/12/2020
 (Signature) *21-12-2020*

NAME: - Ratnesh Paswan,

DESIGNATION: Executive Engineer