FIELD INSPECTION REPORT

nspection: 3	1/12/20	District: Khagaria	M
		Length (thin)	
1 (3-7)	A.J. B. 1	Alash to Ladaura	11.7
	MAINTENANC	10.10	49
No.:	17.		
f the Project:	Ongoing/Compl	eted/Under Maintenance	<u> </u>
Sa Case 02.		Remarks	
	Parameter:	s'to be checked	ACMAI AO
Pavement			The state of the s
Road Junction condition			S/U
			S/U
A to the second			8/U
			<i>S</i> ∫U
Whether free	e from defects	such as visible cracks, exposed ent.	Yes/No
			Yes/No
			Yes/No
AND ARCHARGO TO A CAST OF	Prints of 1 pages.	Thousand the same of the same	
The state of the s			s/srl/U
			74.
Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
The state of the s			S/SRL'U
- Cartinos, 30 (CO)	A THE STREET		
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
Status of ATR's & any others			3
	the Road: Programme: No.: f the Project: a case of: Pavement Road Junction Condition of S Riding Quality Road Camber Whether free aggregates in Contraction Jo Compaction of S Compaction of S Condition of S Conditio	regramme: MAINTENANC No.: the Project: Ongoing/Complete a case of: New Connectivity Parameters Pavement Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects aggregates in case of CC Pavem Contraction Joints provided or recompaction of flank/slope & race Cross Drainage Condition of head walls in Human Condition of Abutment & Wing Condition of railings/slab/appro Road Furniture Whether sign boards/informat stones/Pavement road markings Compliance History	Inspection: 21/12/26 Ithe Road: A.J.B. Alash to Ladaura Programme: MAINTENANCE No.: Road Id No.: Ithe Project: Ongoing/Completed/Under Maintenance a case of: New Connectivity/Up gradation/ Maintenance Parameters to be checked Pavement Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Contraction Joints provided or not (CC Pavement) Gempaction of flenk/slope & raincuts if any Cross Drainage Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Compliance History Compliance History

N.A. old C.D. works

Overall Rating

Satisfactory (S)	X X
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: ASHOK KUMAR
DESIGNATION: Executive Engineer