


FIELD INSPECTION REPORT

Date of Inspection : 19.12.20		District: Kishanganj
Division : Kishanganj - I		Length (km): - 2.50 K.M
Name of the Road: Repair of road from Mahadev Dighi to Vishunpur		
Scheme/Programme: MAINTENANCE		
Package No.: - N.A		Road Id No.: 21205808071
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. - N.A	Yes/No - N.A
f)	Contraction Joints provided or not (CC Pavement) - N.A	Yes/No - N.A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No ATR Pending.

Overall Rating :	Satisfactory (S)	-
	Satisfactory but requires Improvement (SRI)	-
	Unsatisfactory (U)	U

Remarks - Repairing work is start today.


 19/12/20
 (Signature)
 (E.E)

NAME: - Er. Chandrashekhari Azad
 E.E