

FIELD INSPECTION REPORT

Date of Inspection : 20/12/2020	District : Madhepura
Division : Madhepura	Length (km) : 2.70
Name of the Road : Kuma, Phand to Jadhafali	
Scheme/Programme : MAINTENANCE	
Package No. :	Road Id No. : 21004700216
Status of the Project : Ongoing/Completed/Under Maintenance	
Work is a case of : New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

The work has been started. The road is damaged at some places.

Sanjeev Kumar
20/12/2020
(Signature)

NAME:

SANJEEV KUMAR

DESIGNATION:

EXECUTIVE ENGINEER
CE-3rd, RWD, Patna