

FIELD INSPECTION REPORT

Date of Inspection : 21.12.2020		District: Nalanda
Division : Bihar Sahit		Length (km): 1.9 km
Name of the Road: Sore Nagan Road to Koyari Bigha		
Scheme/Programme: MAINTENANCE		MR-3054
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance ✓
Work is a case of:		New Connectivity/Up gradation/ Maintenance ✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No/✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No -
g)	Compaction of flank/slope & raincuts if any	Yes/No/✓ No rain cut
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓ N
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

(Signature) 21.12.2020

NAME: Rana Boman Kumar Singh
DESIGNATION: Executive Engineer.