

# FIELD INSPECTION REPORT

Date of Inspection : 21.12.2020		District: Gorpalgaon	
Division : Gorpalgaon-1.		Length (km): 3.00 Km.	
Name of the Road: Baidu. Tola to Paithanpathi			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance /	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U /
b)	Condition of Surfacing	S/U / Pot holes due to water logging.
c)	Riding Quality	S/U /
d)	Road Camber	S/U /
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No /
f)	Contraction Joints provided or not (CC Pavement)	Yes/No /
g)	Compaction of flank/slope & raincuts if any	Yes/No / raincuts.
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U /
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U /
c)	Condition of railings/slab/approach for Bridges	S/SRI/U /
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No /
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME:

DESIGNATION:

Rakesh Ranjan Pandey.

Executive Engineer.

O/ LE-1.

MA

21.12.2020

(Signature)