


FIELD INSPECTION REPORT

Date of Inspection : 21.12.2020		District: Nalanda
Division : Biharsahar		Length (km): 0.880 Km
Name of the Road: NH82 to primary school, Dault to Mahua by hote. lya. Sher. by		
Scheme/Programme: MAINTENANCE MK-3054		
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance ✓		
Work is a case of: New Connectivity/Up gradation/ Maintenance ✓		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U/U
b)	Condition of Surfacing	S/U/U
c)	Riding Quality	S/U/U
d)	Road Camber	S/U/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No/ND
f)	Contraction Joints provided or not (CC Pavement)	Yes/No -
g)	Compaction of flank/slope & raincuts if any	Yes/No/ND
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No/ND ✓
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	U


 21.12.2020
 (Signature)

NAME: Rana Basim K. Singh
 DESIGNATION: Executive Engineer