

42

FIELD INSPECTION REPORT

pld m/r 3054

Date of Inspection :	21/12/20	District:	Rhejpur
Division :	R.W-3 Jagdishpur	Length (km):	15.70 km
Name of the Road:	Dhawan Belwara to Shikhar		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	10401708056
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NIL

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	(SRI)
Unsatisfactory (U)	

Remarks: Some cautionary boards are missing.
Parapets not painted.

(Signature) *[Signature]*
21/12
E.F
(N.AIS)

NAME: Rectification done or not: Not
Rectification started or not: Yes
Notice issued or not: Yes