

(45)

FIELD INSPECTION REPORT

Inspection : 21/12/2020	District: BHOTPUR
Division: JAGDISHPUR	Length (km): 7.00 Km.
Name of the Road: Def NH-30 to Gurey	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 10404708062
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Remarks: Jaz painting not done 200m Stones not found. Barapels not repaired & painted.

NAME:

Rectification done or not: Not
Rectification started or not: Not
Notice issued or not: NO

(Signature)

No
21/12/20
EE
(N.A. ISHRAJ)