

FIELD INSPECTION REPORT

Date of Inspection: 19/12/2016	Location: Panna	
Division: Bhojpur	Length/km: 1.35 km	
Name of the Road: Bhojpur Bigha Surajpur Road, Bhojpur		
Scheme/Programme: MGNREGS		
Package No:	Road ID No:	
Status of the Project: Ongoing / Completed / Under Maintenance		
Work is a part of: New / Existing / Up gradation / Maintenance		
Sl. No.	Parameters to be checked	Remarks

1. Pavement		
a) Road Joint/spot condition		✓
b) Condition of Surfacing		✓
c) Riding Quality		✓
d) Road Curb		✓
e) Whether free from defects such as visible cracks, exposed aggregate in range of 10% Pavement		Yes/No
f) Construction joints provided as per CC Pavement		Yes/No
g) Compaction of flank ditches & shoulders etc.		✓
2. Cross Drainage		
a) Condition of head walls on storm pipe culverts including the parapets		Satisfactory
b) Condition of Abutments on bridge over storm pipe culverts		Satisfactory
c) Condition of wing walls on bridge over storm pipe culverts		Satisfactory
3. Road Curvature		
a) Whether open to view throughout the alignment. Road km & 20m stretch Pavement road conditions are provided and maintained		✓
4. Compliance History		
a) Status of A.P. & any other		

Overall Rating:

Satisfactory (S)

Satisfactory but requires Improvement (SI)

Unsatisfactory (U)

U

Bhupendra Singh

NAME:

Bhupendra Singh
(Signature)