

# FIELD INSPECTION REPORT

Date of Inspection : 19.12.2020		District: Bannu	
Division : Bannu-1		Length (km): 0.424	
Name of the Road: Pansalla Orsa road to Pansalla Anusaidi Jati Tola			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U
c)	Condition of railings/slab/approach for Bridges	S/SR/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Okumel  
 19.12.2020  
 (Signature)

NAME: DHARMVEER KUMAR

DESIGNATION: J.E.