

FIELD INSPECTION REPORT

Date of Inspection: 17.12.2020 District: Panna
 Division: BCRH Length (km): 0.820 km
 Name of the Road: To Durba chaur to ped nadi ke kharwa se to horizontal
 Scheme/Programme: MAINTENANCE
 Package No: Road Id No:
 Status of the Project: Ongoing Completed Task: ☒ Maintenance
 Work is a case of: New ☒ Extension ☐ Upgradation ☐ Maintenance

Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Section condition	☒
b)	Condition of Surfacing	☒
c)	Riding Quality	☒
d)	Road Number	☒
e)	Whether free from defects such as visible cracks, exposed aggregate, in case of C.C. Pavement	Yes ☒
f)	Construction joints provided or not in Pavement	Yes ☒
g)	Compaction of flank slope & shoulders if any	Yes ☒
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	Satisfactory
b)	Condition of Abutment & Wing walls, Slab in R.C.C. culverts	Satisfactory
c)	Condition of railing/slabs approach for Bridges	Satisfactory
3. Road Furniture		
a)	Whether sign boards/informations customary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes ☒
4. Compliance History		
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SI)

Unsatisfactory (U)

0.820

By: Pratek Singh
 Junior Engineer
 NAME:

Signature