

FIELD INSPECTION REPORT

Date of Inspection :- 19.12.20		District :- Mahasarakham	
Division :- Mahasarakham		Length (Km) :- 0.434	
Name of Road :- P.C.D. Road to Water Pumpstand			
Scheme/Programme :- P.C.D.		Maintenance :-	
Package No. :-		Road ID No. :-	
Status of Project :- E&A given Maint. Work		Ongoing/Complete/Under Maintenance :-	
Work is a case of :-		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction Condition	✓ S/U
b)	Condition of Surface	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No ✓
f)	Construction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	✓ Yes/No
4. Compliance History		
a)	Status of ATR's & any others	✓ No

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)


 19.12.20
 J E / plaudi