FIELD INSPECTION REPORT

Date of I	nspection: 19.12	. 2020	District: SUPAU		
Division	SUPA	VL	Length (km): 1.750)	
Name of the Road: Lo36-Lo41 to Tula Patti (Track 16)					
Scheme/Programme: MAINTENANCE					
Package No.: BR-35R-068 Road Id No.: 21004902060					
Status of the Project: Ongoing/Completed/Under Maintenance					
Work is a case of: New Connectivity/Up gradation/ Maintenance					
SI No.	Parameters to be checked			Remarks	
. 2 1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			ed Yes/No M	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No M	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			ng S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U M	
c)	Condition of railings/slab/approach for Bridges			-S/SRI/U M	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			m Yes/No	
4	Compliance History			A STATE OF THE STA	
a)	Status of ATR's & any	others	to be seen and an additional to		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	11

Mayank fare 19-12-2022 (Signature)

NAME: MAYANK RANA

DESIGNATION: $\mathcal{I} \in$