

FIELD INSPECTION REPORT

Date of Inspection	16.12.2020	District	Purnea
Division	Baisi	Length (km)	3.089 KM
Name of the Road	Ekahuda Bandah to Termy Adidasi Tole.		
Scheme/Programme	MAINTENANCE	MMGSY	
Package No.		Road Id No.	
Status of the Project	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl No.	Parameters to be checked	Remarks	
1.	Pavement	S/U	S
a)	Road Junction condition	S/U	S
b)	Condition of Surfacing	S/U	S
c)	Riding Quality	S/U	S
d)	Road Camber	S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	—
g)	Compaction of flank/slope & raincuts if any	Yes/No	Yes
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: *RB Smeel*
16/12/2020

DESIGNATION:

(Signature)