

## FIELD INSPECTION REPORT

Date of Inspection: - 21.12.20		District: Kishanganj
Division: - Kishanganj-I		Length(km): 2.358 km
Name of the Road: L224 - L253 to Belbani		
Scheme/Programme: PMGSY		
Package No.: BR-18R-081		Road Id No.: 21205802071
Status of the Project: Ongoing/Completed /Under Maintenance		
Work is a case of: New Connectivity/ Up gradation / Maintenance		
S1. No	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction Condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints Provided or not ( CC Pavement)	✓ Yes/No
g)	Compaction of flank / slope & raincuts if any	✓ Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its Painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	✓ S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory(S)	- S -
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

NAME: Radheshyam prajapati  
J.E, Bahadurganj-I

21.12.20  
J.E  
R.W.D (W) Division  
Kishanganj-1