

FIELD INSPECTION REPORT


Date of Inspection: - 21.12.20		District: Kishanganj	
Division: Kishanganj-I		Length(km): 4.33 km	
Name of the Road: PMGSY Kachhara Tola to Sitagachh Tola via Kachhara Tola Madarag			
Scheme/Programme: MMGSY			
Package No.: N/A		Road Id No.: 21205814011	
Status of the Project:		Ongoing/Completed /Under Maintenance	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	

Sl. No	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints Provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank / slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory(S)	- S -
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

NAME: Radheshyam prajapati
J.E, Bahadurganj-I


 20/12/20
 J.E
 R.W.D (W) Division
 Kishanganj-1