

# FIELD INSPECTION REPORT

|                                               |  |                                            |
|-----------------------------------------------|--|--------------------------------------------|
| Date of Inspection : 21.12.20                 |  | District: Muradnagar                       |
| Division : Muradnagar West                    |  | Length (km):                               |
| Name of the Road: Reddyming Road to Bhatnagar |  |                                            |
| Scheme/Programme: MAINTENANCE                 |  | Road Id No.: 31507413016                   |
| Package No.:                                  |  |                                            |
| Status of the Project:                        |  | Ongoing/Completed/Under Maintenance        |
| Work is a case of:                            |  | New Connectivity/Up gradation/ Maintenance |

| Sl. No. | Parameters to be checked                                                                                             | Remarks                  |
|---------|----------------------------------------------------------------------------------------------------------------------|--------------------------|
| 1.      | <b>Pavement</b>                                                                                                      |                          |
| a)      | Road Junction condition                                                                                              | S S/U                    |
| b)      | Condition of Surfacing                                                                                               | U S/U                    |
| c)      | Riding Quality                                                                                                       | U S/U                    |
| d)      | Road Camber                                                                                                          | S S/U                    |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | S Yes/No                 |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | S Yes/No                 |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No                   |
| 2.      | <b>Cross Drainage</b>                                                                                                |                          |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U                  |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S S/SRI/U                |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S S/SRI/U                |
| 3.      | <b>Road Furniture</b>                                                                                                |                          |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Requires Painting Yes/No |
| 4.      | <b>Compliance History</b>                                                                                            |                          |
| a)      | Status of ATR's & any others                                                                                         |                          |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            |     |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U)                          |     |

BS  
21.12.20  
(Signature)

NAME:

Jitendra Kumar

DESIGNATION:

OE