

FIELD INSPECTION REPORT

MARVALL

Date of Inspection : 21.12.2022	District: Muradpur
Division : M-42 off Muradpur West	Length (km):
Name of the Road: Road to Vaidali Bazar, Muradpur to Vaidali Bazar, Muradpur to Vaidali Bazar, Muradpur to Vaidali Bazar	Road Id No.: 3150 741 3077
Scheme/Programme: MAINTENANCE	
Package No.:	
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	U S/U
c)	Riding Quality	U S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Requires Painting Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

21.12.2022
(Signature)

NAME: Jitendra Kumar

DESIGNATION: DE