

FIELD INSPECTION REPORT

Date of Inspection : 21.12.2020		District : E. Champarn
Division : Chakia		Length (Km): 1.400
Name of the Road : State Bank Customer Care To T03 (GTSNY)		
Scheme/Programme :		MAINTENANCE
Package No.:		Road ID No.:
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	'S'
b)	Condition of Surfacing	'S'
c)	Riding Quality	'S'
d)	Road Camber	'S'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	'S'
f)	Contraction Joints provided or not (CC Pavement)	'S'
g)	Compaction of flank/slope & raincuts if any	'U'
2,	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	'S'
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	'S'
c)	Condition of railings/slab/approach for Bridges	
3,	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	'S'
4,	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires improvement (SRI)	SR'
	Unsatisfactory (U)	

Note! - Banks are damaged in some length due to Aug 2020 flood

NAME :

DESIGNATION :

[Signature]

21.12.2020
J.E

(Signature)