

FIELD INSPECTION REPORT

Date of Inspection : 19.12.2020	District: East Champaran
Division : Pakriyal	Length (km): 2.815
Name of the Road: Pratikshalay Ashan Pipra to Matharwa via Lauki Tola	
Scheme/Programme: MAINTENANCE	MMGSY
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance ✓
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	LSU
b)	Condition of Surfacing	LSU
c)	Riding Quality	LSU
d)	Road Camber	LSU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

some damage of Road
is damage due to flood.

19.12.2020
(Signature)

NAME: Dharmendra Kumar

DESIGNATION: JE