

## FIELD INSPECTION REPORT

<b>Date of Inspection :</b>		<b>District:</b> MADHUBANI
<b>Division :</b> JAYNATHAR		<b>Length (km):</b> 1.373 km
<b>Name of the Road:</b> DHAMIBAN TO AKHARI		
<b>Scheme/Programme:</b> MAINTENANCE		
<b>Package No.:</b> BR-21R-536		<b>Road Id No.:</b>
<b>Status of the Project:</b> Ongoing/Completed/Under Maintenance		PM 437
<b>Work is a case of:</b> New Connectivity/Up gradation/ Maintenance		

  

Sl. No.	Parameters to be checked	Remarks
<b>1.</b>	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
<b>2.</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
<b>3.</b>	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
<b>4.</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

  
 19.12.20  
 (Signature)

**NAME:** SUMIAN KUMAR

**DESIGNATION:** ASSISTANT ENGINEER