

FIELD INSPECTION REPORT

M 634 (6/20)

Date of Inspection: 12-12-2020	District: Samastipur
Division: Samastipur	Length (km): 2.095 km
Name of the Road: SH 3 to Chandopatti Manikzohi.	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 32010112070.
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U U
c)	Riding Quality	S/U U
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NO
f)	Contraction Joints provided or not (CC Pavement)	Yes/No YES
g)	Compaction of flank/slope & raincuts if any	Yes/No YES/S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NOT
4.	Compliance History	
a)	Status of ATR's & any others	NA

Remarks - exposed aggregate in CC. portion, & Elevation shoulders.

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI -
Unsatisfactory (U)	- U -

Santosh
14-12-2020

NAME: SANTOSH KR. THAKUR
JE, RWD Samastipur-2

(Signature)

AE

14/12/20
AE