

FIELD INSPECTION REPORT

Date of Inspection :	19/12/20	District:	Nalanda
Division :	Rajgir	Length (km):	1.04km
Name of the Road:	Dhobri Pakki Sadak se Karjara middle school se karjara Tak		
Scheme/Programme:	MAINTENANCE	MNP (4515)	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (H/B/)
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (H/A/)
g)	Compaction of flank/slope & raincuts if any	Yes/No (H/A/)
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U (H/A/)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U (H/A/)
c)	Condition of railings/slab/approach for Bridges	S/SRI/U (H/A/)
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Note maintained Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Ranaprasad Kumar
SE
NAME: Ben

[Signature]
19/12/20
SE
(Signature)