

FIELD INSPECTION REPORT

Date of Inspection : 18/12/20		District: Nalanda	
Division : Rajgir		Length (km): 1.00 km.	
Name of the Road: Barnausa banayli Path se bahera tak			
Scheme/Programme: MAINTENANCE		MNP (4515)	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing Completed ☒ Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance ☒	

Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	☒ S/U	
b)	Condition of Surfacing	☒ S/U	
c)	Riding Quality	S/U	
d)	Road Camber	☒ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	(N/A)
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	(H/A)
g)	Compaction of flank/slope & raincuts if any	Yes/No	(H/N)
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	(N/A)
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	(N/A)
3.	Road Furniture		(N/A)
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	NOTE maintained Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Ramprakash Kumar

NAME: SE
Rajgir


 18/12/20
 SE
 (Signature)