

FIELD INSPECTION REPORT

Date of Inspection : 18.12.2020		District: Nalanda	
Division : Raygir		Length (km): 1.25	
Name of the Road: Rasulia Ekam Path se Masua			
Scheme/Programme: MAINTENANCE		Road Id No.: 4515	
Package No.:		Ongoing/Completed/Under Maintenance ✓	
Status of the Project:		New Connectivity/Up gradation/ Maintenance	
Work is a case of:			
Parameters to be checked			
Sl. No.	Parameters	Remarks	
1	Pavement		✓ S/U
a)	Road Junction condition		✓ S/U
b)	Condition of Surfacing		✓ S/U ✓
c)	Riding Quality		✓ S/U
d)	Road Camber		Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of flank/slope & raincuts if any		
2	Gross Drainage		S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		
3	Road Furniture		✓ Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

NAME: Shiva Prakash Gupta
A E (Be-7)

18.12.2020
(Signature)