

FIELD INSPECTION REPORT

Date of Inspection : 10.12.2020		District: Wopalganj	
Division : W.D. Wopalganj		Length (km): 2.538 km	
Name of the Road: Dildiyga to Govindpur (PMU-4)			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4.	Compliance History		
a)	Status of ATR's & any others	N.A.	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	

Note:- Road length partially affected from flood.

(Signature)

NAME: Rajesh Kumar
DESIGNATION: J.E